

Runways 01/19: 2200 x 60 (ASPH-F)		Coordinates	
		Latitude Longitude	40-59-15.362N 072-31-08.314W
Communications		Navigation	
CTAF/U	122.9	Elevation NM from City Instr Approach	30 01 SE NONE
Owner/Manager		Services	
Owner Manager	MR JAY P WICKHAM	Fuel Airframe Repairs	100LL MINOR
	410 AIRWAY DRIVE P.O. BOX 1432	Engine	MAJOR
	MATTITUCK NY 11952	Attended	ALL/MON-FRI/0800-1630
Phone	(631) 298-8330 x 301	Airline Airport	NO
Fax	(631) 298-8412	Transportation	TAXI
E-mail		Food	OFF - 1.5 MILES
Web site		Lodging	OFF - 13 MILES

TELEDYNE MATTITUCK SERVICES INC

FBO (Location)

(631) 298-8330

Remarks

SHORT FIELD - USUALLY CROSS WIND. ALL TRNG OPS; TAKOF/LNDG PRACTICE AND NIGHT OPERATIONS ARE PROHIBITED.